

168813
D
07 | 04 | 2003

B. 3000

**ANALYSIS OF WATER QUALITY
IN WELL WATER IN THE VICINITY OF AN
INDUSTRIAL ZONE AND ANALYSIS OF
SOURCES AND EFFECTS**

By

U. M.S. RIYANKA
B.Sc (University of Colombo)

Thesis

Submitted in partial fulfillment of the requirements of the

Masters of Science
Forestry and Environment Management

Faculty of Graduate studies
University of Sri- Jayewardenapra
Gangodawila
Nugegoda
Sri Lanka
2002

168813

03rd November 2002

ABSTRACT

The Ratmalana- Moratuwa area located in the south of Colombo has developed as an industrial residential suburb of Colombo in the 1950's. It has been revealed that the environmental problems in the area are very acute due to the activities of large number of industries. About 150 industries are densely packed, within this area. Most of these industries are non- agro based industries they can be categorized in to several groups such as paint industries, galvanising industries, asbestos industries, dyeing and finishing, pharmaceutical industries and battery manufacturing industries. According to an investigation of discharges produced in the area it was found that major part of the effluent was released via surface drainage to Lunawa and Bolgoda Lake. The main issue associated with this industrial pollution is water contamination. Even though many studies have been carried out on surface water contamination, studies on ground water contamination have not been done in detail. The intention of this study was to analyze ground water samples at various sites of the industrial zone and to relate the results to the present industrial activities of the area. From these studies it was found that the chemical oxygen demand (COD) levels far exceed the acceptable portable water quality standards, indicating high chemical pollution. In addition it was found that Chemical pollutants are present in the ground water. Biological oxygen demand (BOD) has exceeded the tolerant limits for portable water level at several locations. The trace metals that exceed the levels are Zn , Fe, Cd, Pb and Ni which had not been noted in a previous study done by De Silva *et al.* (1986)

Low pH values in some of the samples indicate water contamination with acids. Some samples have been contaminated with acids and it was revealed by low pH of some samples. Most industries in the area dispose their effluents directly in to the drainage system without any prior treatments. Ground water contamination is thought to be a direct consequence of these inefficient effluent systems. This study discusses the analytical results of water samples taken from various locations of the industrial area and describes the industrial activities in the area that might have caused this ground water contamination, and discusses possible health effects due to use of polluted water as a source of potable water in this well water.

CONTENTS

CONTENTS	PAGE
List of content	iv
List of Tables	v
List of Figures	vi
Dedication	vii
Abbreviation	viii
Abstract	ix
Chapter 1	
1. Introduction	
1.1 General Introduction	1
1.1.1 Extent and Source of water pollution	2-3
1.1.2 Industrial waste	3-4
1.1.3 Ground water	4-6
1.2 Aim of study	7
1.2.1 Study objectives	7
1.3 Study Location	
1.3.1 Criteria for site selection	7-9
1.3.2 Telawala north and south gramasewaka devisions	9-15
1.3.3 Work plan	16-17
Chapter 2	
2. .Litrature review	17-18
2.1 Industrial waste water flows and loading	18-19
Chapter 3	
3. Methodology	20
3.1 Selection of water quality variable	20-23

3.1.1. Physical Parameters	
3.1.2. Chemical Parameters	
3.2 Identification of pollution sources and the details	23-25
 Chapter 4	
4.Results	26-30
4.1 Results of well water quality analysis	26
4.1.1 pH	27
4.1.2 Conductivity	27
4.1.3 Chemical Oxygen Demand	27-28
4.1.4 Biological Oxygen Demand	28
4.1.5 Hardness	28
4.1.6 Calcium	28
4.1.7 Magnesium	28
4.1.8 Sulphate	28
4.1.9 Nitrate	29
4.1.10 Dissolved solids total solids and suspended solids.	29
4.1.11 Phosphate	29
4.1.12 total iron	29
4.1.13 Heavy metals	20-31
 Chapter 5	
Discussion	32-33
5.1 Possible effects due to the presence of pollutants	33-35
 Chapter 6	
6.1 Conclusion	36
6.2 Recommendations	36-37
 References	38-40
 Appendix 1	
Appendix 11	
Appendix 111	